



# **DF60 45° Corner Assembly**

Version 3.0



















Angle Brackets x 6




Angle Brackets

x 4




Back Frame Foot Pad x 5





Bracket x 4




Horizontal Bracket x 8







M4 Allen Key x 1



Front Panel

Front Frame Foot Pad x 2









M5-Long Screw x30

M5 Washer x 30


M5-Short Screw x 36

M4 Stacking Screw x 28


M5 Nuts x 30

Safety Screw x 1 Stacking Bracket x 5












### You will need

- Side Frame Back Vertical Bar x 2
- Side Frame Front Vertical Bar x 2
- · Side Frame Horizontal Bar x 4
- · Horizontal C-Channel x 4
- · Vertical C-Channel x 4

## Steps to install C-Channel


- **Step 1.** Flatten one end of the C-Channel by pressing the open edges together.
- **Step 2.** Push the compressed tip into the slit of the bar.

**Step 3.** Press down the rest of the C-Channel along the slit of the bar.



### Side Frame Horizontal Bar

Position the bar on any side. Install a Horizontal C-Channel into the top slit of the bar. Repeat for all bars.




## Side Frame Back Vertical Bar

Position the bar with the pilot holes facing the flat surface. Install a Vertical C-Channel into the top slit of the bar. Repeat for all bars.




If you are joining the display cases horizontally, do not insert the C-Channel on the connecting bar.



## Side Frame Front Vertical Bar

Place a bar with the magnets facing down. Install a Vertical C-Channel into the top slit. Repeat for all bars.

If you are joining the display cases horizontally, do not insert the C-Channel on the connecting bar.




### You will need

- M5-Long Screw x 44
- M5-Washer x 44
- Back Frame Right Horizontal Bar x 2
- Back Frame Left Horizontal Bar x 2
- Back Frame Middle Vertical Bar x 2
- Middle Horizontal Bar x 2
- Side Frame Back Vertical Bar x 2
- Side Frame Front Vertical Bar x 2
- Side Frame Horizontal Bar x 4


## Steps to insert M5-Long Screw

- Step 1. Insert the M5-Long Screw fully into the M5-Washer.
- Step 2. Position the screw with washer into the pilot hole on the left side of the bar. Turn clockwise to tighten the screw. Leave a 15mm gap between the washer and bar.
- Step 3. Repeat steps 1-2 for the other side of the bar.
- Step 4. Repeat steps 1-3 for
  - Back Frame Right Horizontal Bar x 2
  - Back Frame Left Horizontal Bar x 2
  - Back Frame Middle Vertical Bar x 2
  - Middle Horizontal Bar x 2
  - Side Frame Back Vertical Bar x 2
  - Side Frame Front Vertical Bar x 2
  - Side Frame Horizontal Bar x 4











































**Step 12.**Prepare the Back Enhancement Bar










**Step 12.**Connecting Back Enhancement Bar between the bars.











**Step 14.** 

